SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-JDY-351

2-JDY-351 · 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT · 9 May 2026 · Zaventem (BE)

Specifications

License Plate Number	2-JDY-351
Manufacturer	TOYOTA
Model	Corolla
Model Versions	1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT
Body Type	5 door hatchback
Color	Silver
Paint Type	Metallic
Production Year	2024
Fuel Type	Hybrid Gasoline

VIN	JTNADADB90J024331
Cylinder Capacity	1.798 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Registration	20-11-2024
Odometer	52.666 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	5

Images






























Accessories

ABS	Electric rear windows
Airbags	Electric windows front
Alloy wheels	Electrically adjustable exterior mirrors
Audio System	Fog lights
Automatic air conditioning	Front & rear parking sensors
Bluetooth car kit	Leather steering wheel
Central door locking	Rear view camera
Centre armrest	Roller cover / parcel shelf
Cruise control	Steering wheel multifunction

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Rear Left	7 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Front Right	5 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Rear Right	7 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Spare Tire Type	Homecomer					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Right	Small dent(s)	Restyle	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	Damaged	Touch-up	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Small scratch(es)	Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Middenstuk	Plastic Repair	No





Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Left	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Overfender	Scratch(es)	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
spoiler FB	Stonechipping	Spotrepair	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper – Front	Small scratch(es)	Middenstuk	Plastic Repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Hood	Scratch(es)	Spray	No

Damage Part	Damage Type	Notes	Repair Type	Acceptable
Interior	Scratch(es)	Instaplijst	Replace	No





Damage Part	Damage Type	Repair Type	Acceptable
Skirt – Right	Scratch(es)	Spray	No