SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-CLV-208

2-CLV-208 · Style TSI 110cv 6v AS · 30 March 2026 · Zaventem (BE)

Specifications

License Plate Number	2-CLV-208
Manufacturer	Volkswagen
Model	T-Cross
Model Versions	Style TSI 110cv 6v AS
Body Type	5 door hatchback
Color	Grey
Paint Type	Metallic
Production Year	2022
KW	81

Fuel Type	Gasoline
VIN	WVGZZZC1ZPY008486
Cylinder Capacity	999 cm3
Transmission Type	Handmatig geschakelde transmissie
First Admission	08-09-2022
Odometer	105.759 Km
Numer Of Keys	2
Interior	Black
Number Headrests	5

Images













VOLKSWAGEN AG

CRIT'Air
1
2CLV20
République
Française

584912168
WVGZZZC1ZF
S285571413
Domicile
Home












Accessories

ABS	Electric windows front
Airbags	Electrically adjustable exterior mirrors
Alloy wheels	Fog lights
Audio System	Front & rear parking sensors
Automatic air conditioning	Leather steering wheel
Bluetooth car kit	Navigation system
Central door locking	Rear view camera
Centre armrest	Roller cover / parcel shelf
Cruise control	Seat heating
Electric rear windows	Steering wheel multifunction

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 mm	Hankook	205 mm	55 mm	17 inch	All Season
Rear Left	3 mm	Hankook	205 mm	55 mm	17 inch	All Season
Front Right	4 mm	Hankook	205 mm	55 mm	17 inch	All Season
Rear Right	3 mm	Hankook	205 mm	55 mm	17 inch	All Season
Spare Tire Type	Compressor					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Left Rear	Damaged	Rim repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Small dent(s)	Restyle	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Door-edge chipped	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Mirror - leftside	Signallight broken	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper – Front	Small scratch(es)	Middenstuk		Yes
			Acceptable	




Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spotrepair	No





Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Front	Damaged	Rim repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Overfender	Small scratch(es)	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	Small dent(s)	Restyle	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	Small dent(s)	Restyle	No





Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Roof	Small scratch(es)	Polish	No




Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No