SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-DDU-228

2-DDU-228 · Move! 1.0 TSI 95cv 5v unicolor · 7 May 2026 · Zaventem (BE)

Specifications

License Plate Number	2-DDU-228
Manufacturer	SEAT
Model	Arona
Model Versions	Move! 1.0 TSI 95cv 5v unicolor
Body Type	5 door hatchback
Color	Grey
Paint Type	Metallic
Production Year	2023
KW	70

Fuel Type	Gasoline
VIN	VSSZZZKJ5PR085204
Cylinder Capacity	999 cm3
Transmission Type	Handmatig geschakelde transmissie
First Admission	15-02-2023
Odometer	78.992 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	5

Images
































Accessories

ABS	Electric rear windows
Airbags	Electric windows front
Alloy wheels	Electrically adjustable exterior mirrors
Audio System	Front & rear parking sensors
Automatic air conditioning	Leather steering wheel
Bluetooth car kit	Navigation system
Central door locking	Rear view camera
Centre armrest	Seat heating
Cruise control	Steering wheel multifunction

Condition

Condition exterior	Adequate	Maintenance Remarks	Olieverversen
Condition interior	Adequate	Previous Repairs	Unknown
Last Maintenance	Unknown		

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 mm	Hankook	205 mm	60 mm	16 inch	All Season
Rear Left	4 mm	Hankook	205 mm	60 mm	16 inch	All Season
Front Right	2 mm	Hankook	205 mm	60 mm	16 inch	All Season
Rear Right	4 mm	Hankook	205 mm	60 mm	16 inch	All Season
Spare Tire Type	None					

Damages






Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Right	Dislocated / Loose	Repair	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	Small dent(s)	Dakstijl	Restyle	No




Damage Part	Damage Type	Repair Type	Acceptable
Windscreen – Front	Chipped	Window Repair	No





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Right	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	Scratch(es)	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Tailgate	Missing	Kapje ruitenwisser	Replace	No





Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No





Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Small dent(s)	Restyle	No





Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper – Front	Scratch(es)	En ontzet	Panelbeating & Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Missing	Compressor	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Trunkshelf	Missing	Replace	No