SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-DNL-297

2-DNL-297 · 1,0 Ecoboost Titanium 125pk · 7 May 2026 · Zaventem (BE)

Specifications

License Plate Number	2-DNL-297
Manufacturer	FORD
Model	Puma
Model Versions	1,0 Ecoboost Titanium 125pk
Body Type	5 door hatchback
Color	Grey
Paint Type	Metallic
Production Year	2023
KW	92

Fuel Type	Gasoline
VIN	WF02XXERK2NA34358
Cylinder Capacity	999 cm3
Transmission Type	Handmatig geschakelde transmissie
First Admission	31-01-2023
Odometer	94.099 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	5

Images































Accessories

ABS	Electric windows front
Airbags	Electrically adjustable exterior mirrors
Audio System	Leather steering wheel
Automatic air conditioning	Navigation system
Bluetooth car kit	Rear parking sensors
Central door locking	Seat heating
Centre armrest	Steering wheel multifunction
Cruise control	Steeringwheel – Heated
Electric rear windows	Windscreen – Heated

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 mm	Goodyear	215 mm	55 mm	17 inch	Summer
Rear Left	1 mm	Goodyear	215 mm	55 mm	17 inch	Summer
Front Right	5 mm	Goodyear	215 mm	55 mm	17 inch	Summer
Rear Right	1 mm	Goodyear	215 mm	55 mm	17 inch	Summer
Spare Tire Type	None					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Right	Stonechipping	Touch-up	No




Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Right Front	Damaged	Replace	No





Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Scratch(es)	Spray	No





Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	Scratch(es)	Dakstijl	Spray	No






Damage Part	Damage Type	Repair Type	Acceptable
Roof	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Skirt – Right	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
spoiler RB	Scratch(es)	Spotrepair	No




Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No






Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Right Rear	Damaged	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Overfender	Small scratch(es)	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Stonechipping	Touch-up	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Dent(s) & Scratch(es)	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
spoiler FB	Small dent(s)	Plastic Repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Overfender	Scratch(es)	Replace	No







Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Trunkshelf	Missing	Replace	No