SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-EHL-200

2-EHL-200 · 1.5 HEV 2WD Dynamic · 7 May 2026 · Zaventem (BE)

Specifications

License Plate Number	2-EHL-200
Manufacturer	TOYOTA
Model	Yaris Cross
Model Versions	1.5 HEV 2WD Dynamic
Body Type	5 door hatchback
Color	Grey
Paint Type	Metallic
Production Year	2023
KW	68

Fuel Type	Hybrid Gasoline
VIN	JTDKBABB70A268982
Cylinder Capacity	1.490 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	12-10-2023
Odometer	54.876 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	5

Images






























Accessories

ABS	Electric rear windows
Airbags	Electric windows front
Audio System	Electrically adjustable exterior mirrors
Automatic air conditioning	Fog lights
Bluetooth car kit	Leather steering wheel
Central door locking	Rear view camera
Centre armrest	Roller cover / parcel shelf
Cruise control	Steering wheel multifunction

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown
Smoked in the car			

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 mm	Falken	205 mm	65 mm	16 inch	All Season
Rear Left	6 mm	Falken	205 mm	65 mm	16 inch	All Season
Front Right	4 mm	Falken	205 mm	65 mm	16 inch	All Season
Rear Right	6 mm	Falken	205 mm	65 mm	16 inch	All Season
Spare Tire Type	None					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
spoiler RB	Scratch(es)	Plastic Repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Left Front	Damaged	Replace	No






Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Right Front	Damaged	Replace	No





Damage Part	Damage Type	Repair Type	Acceptable
Overfender	Scratch(es)	Replace	No