SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-ENX-178

2-ENX-178 · 1.5 HEV 2WD Dynamic 1.5 116PS AT · 8 May 2026 · Zaventem (BE)

Specifications

License Plate Number	2-ENX-178
Manufacturer	TOYOTA
Model	Yaris Cross
Model Versions	1.5 HEV 2WD Dynamic 1.5 116PS AT
Body Type	5 door hatchback
Color	Grey
Paint Type	Metallic
Production Year	2023
Fuel Type	Hybrid Gasoline

VIN	JTDKBABB90A265050
Cylinder Capacity	1.500 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	05-12-2023
Odometer	85.260 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	5

Images









Yaris Cross Hybrid




TOYOTA MOTOR CORPORATION
JTDKBABB90A265050
1670kg
2445kg
993kg
925kg
MXPJNL-BHXNBW














Accessories

ABS	Electric rear windows
Airbags	Electric windows front
Audio System	Electrically adjustable exterior mirrors
Automatic air conditioning	Fog lights
Bluetooth car kit	Leather steering wheel
Central door locking	Rear view camera
Centre armrest	Roller cover / parcel shelf
Cruise control	Steering wheel multifunction

Condition

Condition exterior	Adequate	Last Maintenance	16-03-2026
Condition interior	Adequate	Last maintenance odometer	79.374
Smoked in the car		Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 mm	Hankook	205 mm	65 mm	16 inch	All Season
Rear Left	6 mm	Hankook	205 mm	65 mm	16 inch	All Season
Front Right	6 mm	Hankook	205 mm	65 mm	16 inch	All Season
Rear Right	6 mm	Hankook	205 mm	65 mm	16 inch	All Season
Spare Tire Type	Compressor					

Damages





Damage Part	Damage Type	Repair Type	Acceptable
Dashboard	Scratch(es)	Plastic Repair	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Reardoor – Right	Scratch(es)	Binnenzijde	Plastic Repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Right Front	Scratch(es)	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	Small dent(s)	Restyle	No






Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	small dents / small scratches	Panelbeating & Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Interior	Missing	Vloermat	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Drivers seat	Burned	Cloth Repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Left Front	Damaged	Replace	No