


2-ENX-178

2-ENX-178 · 1.5 HEV 2WD Dynamic 1.5 116PS AT · 8 May 2026 · Zaventem (BE)

Specifications

License Plate Number	2-ENX-178	VIN	JTDKBABB90A265050
Manufacturer	TOYOTA	Cylinder Capacity	1.500 ^{cm³}
Model	Yaris Cross	Transmission Type	Automatisch geschakelde Transmissie
Model Versions	1.5 HEV 2WD Dynamic 1.5 116PS AT	First Admission	05-12-2023
Body Type	5 door hatchback	Odometer	85.260 ^{Km}
Color	Grey	Numer Of Keys	2
Paint Type	Metallic	Interior	Grey
Production Year	2023	Number Headrests	5
Fuel Type	Hybrid Gasoline		

Images





Accessories

ABS

Airbags

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Leather steering wheel

Rear view camera

Roller cover / parcel shelf

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Smoked in the car

Last Maintenance 16-03-2026

Last maintenance odometer 79.374

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 ^{mm}	Hankook	205 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Rear Left	6 ^{mm}	Hankook	205 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Front Right	6 ^{mm}	Hankook	205 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Rear Right	6 ^{mm}	Hankook	205 ^{mm}	65 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	Compressor					

Damages



Damage Part

Damage Type

Repair Type

Acceptable

Dashboard

Scratch(es)

Plastic Repair

No



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Reardoor - Right

Scratch(es)

Binnenzijde

No

Plastic Repair



Damage Part

Damage Type

Repair Type

Acceptable

Wheelcover - Right Front

Scratch(es)

Replace

No




Damage Part
Frontdoor - Right

Damage Type
Small dent(s)

Repair Type
Restyle

Acceptable
No



Damage Part
Bumper - Rear

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Fender - Rear Left


Damage Type
small dents / small scratches

Repair Type
Panelbeating & Spray

Acceptable
No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Interior	Missing	Vloermat	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Drivers seat	Burned	Cloth Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Wheelcover - Left Front	Damaged	Replace	No