SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-FAJ-879

2-FAJ-879 · Move 1.0 110PS AT / Winter-Paket · 8 May 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FAJ-879
Manufacturer	SEAT
Model	Arona
Model Versions	Move 1.0 110PS AT / Winter-Paket
Body Type	5 door hatchback
Color	Blue
Paint Type	Metallic
Production Year	2024
Fuel Type	Gasoline

VIN	VSSZZZKJ5RR087487
Cylinder Capacity	999 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	06-03-2024
Odometer	65.237 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	5

Images
































Accessories

ABS	Electric windows front
Airbags	Electrically adjustable exterior mirrors
Alloy wheels	Front & rear parking sensors
Audio System	Leather steering wheel
Automatic air conditioning	Navigation system
Bluetooth car kit	Rear view camera
Central door locking	Roller cover / parcel shelf
Centre armrest	Seat heating
Cruise control	Steering wheel multifunction
Electric rear windows	

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Maintenance Remarks	Olieverversen over 12400 km
Smoked in the car		Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	1 mm	Hankook	205 mm	60 mm	16 inch	All Season
Rear Left	5 mm	Hankook	205 mm	60 mm	16 inch	All Season
Front Right	5 mm	Continental	205 mm	60 mm	16 inch	Summer
Rear Right	5 mm	Hankook	205 mm	60 mm	16 inch	All Season
Spare Tire Type	Compressor					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Windscreen – Front	Chipped	Window Repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Small dent(s)	Restyle	No




Damage Part	Damage Type	Repair Type	Acceptable
Alloy – Right Front	Damaged	Rim repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Overfender	Small scratch(es)	Acceptable	Yes




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Tailgate	Scratch(es)	Spoiler	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Overfender	Scratch(es)	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
spoiler RB	Scratch(es)	Plastic Repair	No





Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No





Damage Part	Damage Type	Notes	Repair Type	Acceptable
Interior	Burned	Vloerbedekking	Cloth Repair	No

Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Left	Small dent(s)	Restyle	No