

2-FAW-662

2-FAW-662 · 1.5 HEV 2WD Dynamic · 7 May 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FAW-662	Fuel Type	Hybrid Gasoline
Manufacturer	TOYOTA	VIN	JTDKBABB90A269065
Model	Yaris Cross	Cylinder Capacity	1.490 ^{cm³}
Model Versions	1.5 HEV 2WD Dynamic	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	11-03-2024
Color	Grey	Odometer	81.600 ^{km}
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	68	Number Headrests	5

Images





Accessories

ABS

Airbags

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Leather steering wheel

Rear view camera

Roller cover / parcel shelf

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 ^{mm}	Pirelli	215 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Left	5 ^{mm}	Pirelli	215 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Front Right	2 ^{mm}	Pirelli	215 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Rear Right	5 ^{mm}	Pirelli	215 ^{mm}	60 ^{mm}	16 ^{inch}	All Season
Spare Tire Type	None					

Damages



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper - Front	Broken	Steuntje	Replace	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Grille	Dent(s)	Onder	Replace	No



Damage Part	Damage Type	Repair Type	Acceptable
Bumper - Front	small dents / small scratches	Panelbeating & Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	Hail Damage	Dakstijl >20	Restyle	No



Damage Part	Damage Type	Repair Type	Acceptable
Mirror - Rightside	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Right	small dents / small scratches	Panelbeating & Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Tailgate	Hail Damage	>30	Restyle	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Left	Scratch(es)	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	Hail Damage	>250	Panelbeating & Spray	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	Hail Damage	Dakstijl >30	Restyle	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Reardoor - Left	Hail Damage	>10	Restyle	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Frontdoor - Left	Hail Damage	>30	Restyle	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Fender - Front Left	Hail Damage	>30	Restyle	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Hood	Hail Damage	>200	Replace & Spray	No

