

## 2-FGV-187

2-FGV-187 · FR 1,0L TSI 110HP DSG KJ75RZ E05 · 7 May 2026 · Zaventem (BE)

### Specifications

License Plate Number	2-FGV-187	Fuel Type	Gasoline
Manufacturer	SEAT	VIN	VSSZZZKJ8RR122622
Model	Arona	Cylinder Capacity	999 <sup>cm<sup>3</sup></sup>
Model Versions	FR 1,0L TSI 110HP DSG KJ75RZ E05	Transmission Type	Automatisch geschakelde Transmissie
Body Type	5 door hatchback	First Admission	06-05-2024
Color	Grey	Odometer	80.026 <sup>Km</sup>
Paint Type	Metallic	Numer Of Keys	2
Production Year	2024	Interior	Grey
KW	85	Number Headrests	5

# Images





## Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Front & rear parking sensors

Leather steering wheel

Navigation system

Rear view camera

Roller cover / parcel shelf

Seat heating

Steering wheel multifunction

## Condition

Condition exterior Adequate Maintenance Remarks Olieverversen over 5600 km

Condition interior Adequate Previous Repairs Unknown

## Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 <sup>mm</sup>	Goodyear	205 <sup>mm</sup>	55 <sup>mm</sup>	17 <sup>inch</sup>	Summer
Rear Left	5 <sup>mm</sup>	Goodyear	205 <sup>mm</sup>	55 <sup>mm</sup>	17 <sup>inch</sup>	Summer
Front Right	4 <sup>mm</sup>	Goodyear	205 <sup>mm</sup>	55 <sup>mm</sup>	17 <sup>inch</sup>	Summer
Rear Right	5 <sup>mm</sup>	Goodyear	205 <sup>mm</sup>	55 <sup>mm</sup>	17 <sup>inch</sup>	Summer
Spare Tire Type	None					

## Damages



Damage Part	Damage Type	Repair Type	Acceptable
Skirt - Right	Scratch(es)	Plastic Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor - Right	small dents / small scratches	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Right	small dents / small scratches	Touch-up / Polish	No



Damage Part

Damage Type

Repair Type

Acceptable

Tailgate

small dents / small scratches

Restyle / Touch-up

No



Damage Part

Damage Type

Repair Type

Acceptable

spoiler RB

Scratch(es)

Plastic Repair

No



Damage Part

Damage Type

Notes

Repair Type

Acceptable

Roof

Small dent(s)

Dakstijl

Restyle

No



Damage Part	Damage Type	Repair Type	Acceptable
Fender - Rear Left	small dents / small scratches	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Reardoor - Left	Dent(s)	Panelbeating & Spray	No



Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Missing	Compressor	Replace	No