SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-FGV-187

2-FGV-187 · FR 1,0L TSI 110HP DSG KJ75RZ E05 · 7 May 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FGV-187
Manufacturer	SEAT
Model	Arona
Model Versions	FR 1,0L TSI 110HP DSG KJ75RZ E05
Body Type	5 door hatchback
Color	Grey
Paint Type	Metallic
Production Year	2024
KW	85

Fuel Type	Gasoline
VIN	VSSZZZKJ8RR122622
Cylinder Capacity	999 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	06-05-2024
Odometer	80.026 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	5

Images
































Accessories

ABS	Electric windows front
Airbags	Electrically adjustable exterior mirrors
Alloy wheels	Front & rear parking sensors
Audio System	Leather steering wheel
Automatic air conditioning	Navigation system
Bluetooth car kit	Rear view camera
Central door locking	Roller cover / parcel shelf
Centre armrest	Seat heating
Cruise control	Steering wheel multifunction
Electric rear windows	

Condition

Condition exterior	Adequate	Maintenance Remarks	Olieverversen over 5600 km
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	4 mm	Goodyear	205 mm	55 mm	17 inch	Summer
Rear Left	5 mm	Goodyear	205 mm	55 mm	17 inch	Summer
Front Right	4 mm	Goodyear	205 mm	55 mm	17 inch	Summer
Rear Right	5 mm	Goodyear	205 mm	55 mm	17 inch	Summer
Spare Tire Type	None					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Skirt – Right	Scratch(es)	Plastic Repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Right	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	small dents / small scratches	Touch-up / Polish	No






Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	small dents / small scratches	Restyle / Touch-up	No




Damage Part	Damage Type	Repair Type	Acceptable
spoiler RB	Scratch(es)	Plastic Repair	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	Small dent(s)	Dakstijl	Restyle	No





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	small dents / small scratches	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Dent(s)	Panelbeating & Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Interior	Stains & dirt	Cleaning	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Other	Missing	Compressor	Replace	No