Technician
Rutger Koogh

2-FGV-200

2-FGV-200 · Move! Full link 1,0L TSI 110HP DSG KJ72RZ E06 · 7 May 2026 · Zaventem (BE)

Specifications

License Plate Number	2-FGV-200
Manufacturer	SEAT
Model	Arona
Model Versions	Move! Full link 1,0L TSI 110HP DSG KJ72RZ E06
Body Type	5 door hatchback
Color	Black
Paint Type	Metallic
Production Year	2024
KW	85

Fuel Type	Gasoline
VIN	VSSZZZKJ2RR122566
Cylinder Capacity	999 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	06-05-2024
Odometer	73.446 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	5

Images






























Accessories

ABS	Cruise control
Airbags	Electric rear windows
Alloy wheels	Electric windows front
Audio System	Electrically adjustable exterior mirrors
Automatic air conditioning	Leather steering wheel
Bluetooth car kit	Rear parking sensors
Central door locking	Seat heating
Centre armrest	Steering wheel multifunction

Condition

Condition exterior	Adequate	Maintenance Remarks	Bandenspanning controleren Olieverversen over 13700 km
Condition interior	Adequate	Previous Repairs	Unknown
Last Maintenance	Unknown		

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 mm	Goodyear	205 mm	55 mm	17 inch	Summer
Rear Left	4 mm	Goodyear	205 mm	55 mm	17 inch	Summer
Front Right	2 mm	Goodyear	205 mm	55 mm	17 inch	Summer
Rear Right	4 mm	Goodyear	205 mm	55 mm	17 inch	Summer
Spare Tire Type	Compressor					

Damages





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Scratch(es)	Spray	No






Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Left	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Trunkshelf	Missing	Replace	No