SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-GBT-666

2-GBT-666 · 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT · 7 May 2026 · Zaventem (BE)

Specifications

License Plate Number	2-GBT-666
Manufacturer	TOYOTA
Model	Corolla
Model Versions	1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT
Body Type	5 door hatchback
Color	Black
Paint Type	Metallic
Production Year	2024
Fuel Type	Hybrid Gasoline

VIN	JTNADADBX0J021938
Cylinder Capacity	1.798 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	17-10-2024
Odometer	30.886 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	5

Images



























UNIROYAL

Accessories

ABS	Electric rear windows
Airbags	Electric windows front
Alloy wheels	Electrically adjustable exterior mirrors
Audio System	Fog lights
Automatic air conditioning	Leather steering wheel
Bluetooth car kit	Rear parking sensors
Central door locking	Rear view camera
Centre armrest	Roller cover / parcel shelf
Cruise control	Steering wheel multifunction

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Rear Left	7 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Front Right	6 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Rear Right	7 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Spare Tire Type	Homecomer					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Taillight – Left	Small scratch(es)	Polish	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Front Right	Dent(s)	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Small dent(s)	Restyle	No





Damage Part	Damage Type	Repair Type	Acceptable
spoiler RB	Scratch(es)	Plastic Repair	No







Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Rear	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Small dent(s)	Restyle	No





Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes