

2-GBT-666

2-GBT-666 · 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT · 7 May 2026 ·
Zaventem (BE)

Specifications

License Plate Number	2-GBT-666	VIN	JTNADADBX0J021938
Manufacturer	TOYOTA	Cylinder Capacity	1.798 ^{cm³}
Model	Corolla	Transmission Type	Automatisch geschakelde Transmissie
Model Versions	1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT	First Admission	17-10-2024
Body Type	5 door hatchback	Odometer	30.886 ^{Km}
Color	Black	Numer Of Keys	2
Paint Type	Metallic	Interior	Grey
Production Year	2024	Number Headrests	5
Fuel Type	Hybrid Gasoline		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Leather steering wheel

Rear parking sensors

Rear view camera

Roller cover / parcel shelf

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Rear Left	7 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Front Right	6 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Rear Right	7 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	Homecomer					

Damages



Damage Part
Taillight - Left

Damage Type
Small scratch(es)

Repair Type
Polish

Acceptable
No



Damage Part
Fender - Front Right

Damage Type
Dent(s)

Repair Type
Panelbeating & Spray

Acceptable
No



Damage Part
Fender - Rear Right

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Tailgate

Damage Type
Small dent(s)

Repair Type
Restyle

Acceptable
No



Damage Part
spoiler RB

Damage Type
Scratch(es)

Repair Type
Plastic Repair

Acceptable
No



Damage Part
Bumper - Rear

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Fender - Rear Left

Damage Type
Small dent(s)

Repair Type
Restyle

Acceptable
No



Damage Part
Frontdoor - Left

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes