SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-GDK-484

2-GDK-484 · 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT · 8 May 2026 · Zaventem (BE)

Specifications

License Plate Number	2-GDK-484
Manufacturer	TOYOTA
Model	Corolla
Model Versions	1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT
Body Type	5 door hatchback
Color	Black
Paint Type	Metallic
Production Year	2024
Fuel Type	Hybrid Gasoline

VIN	JTNADADB10J023478
Cylinder Capacity	1.798 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	05-11-2024
Odometer	41.939 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	5

Images






























Accessories

ABS	Electric windows front
Airbags	Electrically adjustable exterior mirrors
Alloy wheels	Fog lights
Audio System	Front & rear parking sensors
Automatic air conditioning	Leather steering wheel
Bluetooth car kit	Navigation system
Central door locking	Rear view camera
Centre armrest	Roller cover / parcel shelf
Cruise control	Steering wheel multifunction
Electric rear windows	

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	6 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Rear Left	7 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Front Right	6 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Rear Right	7 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Spare Tire Type	None					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	Scratch(es)	Spray	No






Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Scratch(es)	Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
spoiler RB	Scratch(es)	Plastic Repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Roof	Small dent(s)	Restyle	No




Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	Small dent(s)	Restyle / Touch-up	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Door-edge chipped	Acceptable	Yes




Damage Part	Damage Type	Notes	Repair Type	Acceptable
spoiler FB	Scratch(es)	En ontzet	Panelbeating & Spotrepair	No




Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Scratch(es)	Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Hood	Scratch(es)	Spray	No