

2-GDK-486

2-GDK-486 · 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT · 7 May 2026 · Zaventem (BE)

Specifications

License Plate Number	2-GDK-486	VIN	JTNADADB20J023554
Manufacturer	TOYOTA	Cylinder Capacity	1.798 ^{cm³}
Model	Corolla	Transmission Type	Automatisch geschakelde Transmissie
Model Versions	1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT	First Admission	05-11-2024
Body Type	5 door hatchback	Odometer	44.536 ^{Km}
Color	Black	Numer Of Keys	2
Paint Type	Metallic	Interior	Grey
Production Year	2024	Number Headrests	5
Fuel Type	Hybrid Gasoline		

Images





Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Leather steering wheel

Navigation system

Rear parking sensors

Rear view camera

Roller cover / parcel shelf

Steering wheel multifunction

Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Rear Left	6 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Front Right	5 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Rear Right	6 ^{mm}	Uniroyal	215 ^{mm}	60 ^{mm}	17 ^{inch}	All Season
Spare Tire Type	Homecomer					

Damages



Damage Part

Damage Type

Repair Type

Acceptable

Windscreen - Front

Broken

Replace

No



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Front Right

Small dent(s)

Restyle

No



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Rear Right

Small dent(s)

Restyle

No



Damage Part
Reardoor - Left

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part
Fender - Rear Left

Damage Type
small dents / small scratches

Repair Type
Panelbeating & Spray

Acceptable
No



Damage Part
Fender - Front Left

Damage Type
Scratch(es)

Repair Type
Spray

Acceptable
No



Damage Part	Damage Type	Repair Type	Acceptable
Hood	Small dent(s)	Restyle	No