SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Rutger Koogh

2-GDK-511

2-GDK-511 · 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT · 8 May 2026 · Zaventem (BE)

Specifications

License Plate Number	2-GDK-511
Manufacturer	TOYOTA
Model	Corolla
Model Versions	1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT
Body Type	5 door hatchback
Color	Black
Paint Type	Metallic
Production Year	2024
Fuel Type	Hybrid Gasoline

VIN	JTNADADB50J024200
Cylinder Capacity	1.798 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	05-11-2024
Odometer	50.308 Km
Numer Of Keys	2
Interior	Grey
Number Headrests	5

Images













TOYOTA MOTOR CORPORATION






0
P
Oil Maintenance Required
Visit Your Dealer
-719 km








Accessories

ABS	Electric rear windows
Airbags	Electric windows front
Alloy wheels	Electrically adjustable exterior mirrors
Audio System	Fog lights
Automatic air conditioning	Front & rear parking sensors
Bluetooth car kit	Leather steering wheel
Central door locking	Navigation system
Centre armrest	Rear view camera
Cruise control	Steering wheel multifunction

Condition

Condition exterior	Adequate	Maintenance Remarks	Olieverversen
Condition interior	Adequate	Previous Repairs	Unknown
Last Maintenance	Unknown		

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	5 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Rear Left	7 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Front Right	5 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Rear Right	7 mm	Uniroyal	215 mm	60 mm	17 inch	All Season
Spare Tire Type	Homecomer					

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Trunkshelf	Missing	Replace	No





Damage Part	Damage Type	Repair Type	Acceptable
Tailgate	Damaged	Touch-up	No




Damage Part	Damage Type	Repair Type	Acceptable
Drivers seat	Burned	Cloth Repair	No




Damage Part	Damage Type	Notes	Repair Type	Acceptable
Frontdoor – Left	Small dent(s)	Binnenzijde	Cloth Repair	No




Damage Part	Damage Type	Repair Type	Acceptable
Rear seat	Stains & dirt	Cleaning	No





Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Left	small dents / small scratches	Panelbeating & Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	small dents / small scratches	Panelbeating & Spray	No





Damage Part	Damage Type	Repair Type	Acceptable
Hood	Stonechipping	Acceptable	Yes





Damage Part	Damage Type	Repair Type	Acceptable
Windscreen – Front	Broken	Replace	No