

## 2-JDY-351

2-JDY-351 · 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT · 9 May 2026 ·  
Zaventem (BE)

### Specifications

License Plate Number	2-JDY-351	VIN	JTNADADB90J024331
Manufacturer	TOYOTA	Cylinder Capacity	1.798 <sup>cm<sup>3</sup></sup>
Model	Corolla	Transmission Type	Automatisch geschakelde Transmissie
Model Versions	1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT	First Registration	20-11-2024
Body Type	5 door hatchback	Odometer	52.666 <sup>Km</sup>
Color	Silver	Numer Of Keys	2
Paint Type	Metallic	Interior	Grey
Production Year	2024	Number Headrests	5
Fuel Type	Hybrid Gasoline		





## Accessories

ABS

Airbags

Alloy wheels

Audio System

Automatic air conditioning

Bluetooth car kit

Central door locking

Centre armrest

Cruise control

Electric rear windows

Electric windows front

Electrically adjustable exterior mirrors

Fog lights

Front & rear parking sensors

Leather steering wheel

Rear view camera

Roller cover / parcel shelf

Steering wheel multifunction

## Condition

Condition exterior Adequate

Condition interior Adequate

Last Maintenance Unknown

Previous Repairs Unknown

## Tire Specifications

<b>Tire</b>	<b>Profile</b>	<b>Brand</b>	<b>Width</b>	<b>Aspect Ratio</b>	<b>Radial</b>	<b>Type</b>
Front Left	5 <sup>mm</sup>	Uniroyal	215 <sup>mm</sup>	60 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Rear Left	7 <sup>mm</sup>	Uniroyal	215 <sup>mm</sup>	60 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Front Right	5 <sup>mm</sup>	Uniroyal	215 <sup>mm</sup>	60 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Rear Right	7 <sup>mm</sup>	Uniroyal	215 <sup>mm</sup>	60 <sup>mm</sup>	17 <sup>inch</sup>	All Season
Spare Tire Type	Homecomer					

## Damages



Damage Part

Damage Type

Repair Type

Acceptable

Fender - Front Right

Small dent(s)

Restyle

No



Damage Part

Damage Type

Repair Type

Acceptable

Frontdoor - Right

Damaged

Touch-up

No



Damage Part

Damage Type

Repair Type

Acceptable

Reardoor - Right

Scratch(es)

Spray

No



Damage Part  
Fender - Rear Right

Damage Type  
Small scratch(es)

Repair Type  
Spray

Acceptable  
No



Damage Part  
Bumper - Rear

Damage Type  
Scratch(es)

Notes  
Middenstuk

Repair Type  
Plastic Repair  
Acceptable  
No



Damage Part  
Frontdoor - Left

Damage Type  
Scratch(es)

Repair Type  
Spray

Acceptable  
No



Damage Part

Damage Type

Repair Type


Acceptable

Fender - Front Left

small dents / small scratches

Panelbeating & Spray

No



Damage Part

Damage Type

Repair Type

Acceptable

Overfender

Scratch(es)

Replace

No



Damage Part

Damage Type

Repair Type

Acceptable

Bumper - Front

Scratch(es)

Spray

No





Damage Part	Damage Type	Repair Type	Acceptable
spoiler FB	Stonechipping	Spotrepair	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Bumper - Front	Small scratch(es)	Middenstuk	Plastic Repair	No



Damage Part	Damage Type	Repair Type	Acceptable
Hood	Scratch(es)	Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Interior	Scratch(es)	Instaplijst	Replace	No



Damage Part

Damage Type

Repair Type

Acceptable

Skirt - Right

Scratch(es)

Spray

No